## **JOB STORY**


**Boulder Breaking:** Allan A Myers Company Subdivision Chester, PA

Dā-mite

The Boulders were Delaware "Blue Rock" which is a basalt.

Big breakers will not break this rock. It is so hard that it is not crushed for aggregate.

64 mm and 42 mm holes were drilled. The first rock was loaded with Da-mite about 9:30 am and started showing cracks about 12:30 pm and was broken into many pieces by 2:30 pm.





Pieces were still so big they were drilled again to break them down further.