

JOB STORY

Concrete:

Foundation Removal
Mocksville, North Carolina



Da-mite

Air Compressor Factory
Mocksville, North Carolina.
Project involved fracturing
and removal of concrete
foundations that were
under floor in the plant.
Vibration and dust were of
high concern. Contractor
used rock drills, with water
dust control, to drill the
holes. Rebar was spaced
on 1 foot centers. Holes
were drilled on 1 foot
centers to ease drilling.
There was no vertical steel
in the foundations. Once
fractured, an excavator
was able to shake the
foundations apart and
remove them.

Crew drilling with wet drills
for dust control. (top)

Daigh "pre-split"
foundation so only half of
it had to be removed.





Fractured foundation



Digging fractured foundation with loader backhoe.



Daigh Company, Inc. 2393 Canton Hwy, Suite 400, Cumming, GA 30040
P: 770-886-4711 F: 770-887-3783 sales@daighcompany.com www.da-mite.com