

## JOB STORY

**Mass Rock:**  
Outcropping Excavation  
Foundation

**Da-mite**



Mass Rock/Outcropping:  
Rock: Pegmatite  
Holes drilled: 1 7/8" diameter  
holes, depth 8-10' deep  
Problem: impact hammers  
would not break the rock.  
Explosives could not be used  
due to confined space.

Holes being drilled with 1 7/8"  
diameter holes, 8-10' deep.  
(Top Photo)

Workers pouring Da-mite  
into the holes at 2pm in the  
afternoon.



Rock fractured by Da-mite within 18 hours.



Contractor able to break down and excavate the rock within minutes after Da-mite fractured the rock.



Daigh Company, Inc. 2393 Canton Hwy, Suite 400, Cumming, GA 30040  
P: 770-886-4711 F: 770-887-3783 sales@daighcompany.com [www.da-mite.com](http://www.da-mite.com)